



Photo 3. Severed Tail Rotor Drive Shaft End 1 (Photo Courtesy of Air Force Fun Inc.)