



Photo 4. Severed Tail Rotor Drive Shaft End 2 (Photo Courtesy of FAA)