



Photo 1 – Accident Site – Courtesy of VSP



Photo 2 – Main Wreckage – Courtesy of VSP



Photo 3 – Close Up of Main Wreckage – Courtesy of VSP



Photo 4 – Engine and Propeller Hub – Courtesy of FAA



Photo 5 – Propeller Hub with Blade Missing – Courtesy of FAA



Photo 6 – Close Up of Propeller Hub Showing Fractured Blade Root – Courtesy of FAA



Photo 7 – Blade Root Fracture Face Displaying Fatigue Features