



**Photo 1 – Starboard Side View of Accident Airplane at FL250 (Courtesy of United States Air Force Air National Guard)**



**Photo 2 – Port Side View of Accident Airplane at FL250 (Courtesy of United States Air Force Air National Guard)**



**Photo 3 – Starboard Side View of Accident Airplane at FL250 (Courtesy of United States Air Force Air National Guard)**



**Photo 4 – View of Accident Airplane Emergency Exit Window During Accident Flight (Courtesy of United States Air Force Air National Guard)**



**Photo 5 – View of a TBM900 Emergency Exit Door**



**Photo 6 – View of Oil Slick and Debris Located During Search Effort (Courtesy of Jamaican Civil Aviation Authority)**