



Photo 1 – View of Initial Impact Crater



Photo 2 – View of Debris Path and Aft Fuselage



Photo 3 – View of Propeller System



Photo 4 – View of Slashed Tree Trunk with Paint Transfer (FAA)



Photo 5 – View of Slashed Tree Trunk