



Photo 1 – NTSB Digital Photograph. Aerial view Depicting the Accident Site Location Reference to the Runway.



Photo 2 - NTSB Digital Photograph. Close-Up Aerial View of the Accident Site. Note the fuel sheen on the water.



Photo 3 - NTSB Digital Photograph. Ground View of the Main Wreckage at the Accident Site. Note the fragmentation.



Photo 4 - NTSB Digital Photograph. View Depicting the Engine Assembly with Attached Firewall Being Removed from the Water.



Photo 5 - NTSB Digital Photograph. View Depicting the Cockpit and Empennage.



Photo 6 - NTSB Digital Photograph. Left Side View of the Empennage.



Photo 7 - NTSB Digital Photograph. Right Side View of the Empennage. Note the damaged Right Horizontal Stabilizer.



Photo 8 - NTSB Digital Photograph. Rear View of the Empennage.



Photo 9 - NTSB Digital Photograph. View Depicting the Left Wing.



Photo 10 - NTSB Digital Photograph. View of the Fragmented Right Wing.



Photo 11 - NTSB Digital Photograph. View of the Throttle Quadrant.



Photo 12 - NTSB Digital Photograph. Left Side View of the Rear Seat Control Stick and Control Stick Base. Note the bulging on the Forward Portion of the Control Stick.



Photo 13 - NTSB Digital Photograph. Close-Up view of the Left Side of the Rear Seat Control Stick. Note the Bulging on the Forward Portion of the Control Stick.



Photo 14 - NTSB Digital Photograph. Close-Up view of the Left Side of the Rear Seat Control Stick Base. Note the Deformation of the Upper Portion of the Hole.