



Photo 1 – Initial tree strikes



Photo 2 – Main wreckage



Photo 3 – Engine and debris at accident site (view 1)



Photo 4 – Engine and debris at accident site (view 2)



Photo 5 – Engine at accident site



Photo 6 – Engine at recovery facility



Photo 7 – Engine inlet



Photo 8 – Wreckage layout at recovery facility



Photo 9 – Cockpit push-pull control tubes



Photo 10 – Discharged ejection seat rocket motor



Photo 11 – Undischarged ejection seat rocket motor