

<u>NATIONAL TRANSPORTATION SAFETY BOARD</u>		Time 3:00 pm	Date 3/5/2015
RECORD OF: ☐ VISIT ☐ CONFERENCE ☒ TELEPHONE CALL			
Name (s) of Person (s) contacted or in conference and location		Routing	
Florida Air Recovery		Symbol	Initials
Subject: N3940H-Beaver County Airport (BVI)			
Digest: In a telephone discussion with personnel from Florida Air Recovery, they stated that during the recovery of N2122K; approximately 18 gallons of fuel was de-fuel from the left fuel tank during the recovery. No fuel was noted in the right tank and the fuel lines were breached. The airplane remained on the accident site for 5 days before recovery.			
Conclusions, Action Taken, or Required:			
Date 3/5/2015	Title ASI	Signature Alleyne	