



Photo 1 – Forward View of Helicopter at Accident Site (Courtesy of FAA)



Photo 2 – Aft View of Main Wreckage at Accident Site (Courtesy of FAA)



Photo 3 – View of Tailboom (Courtesy of FAA)



Photo 4 – Elastomeric Bearings Recovered from Accident Airplane



Photo 5 – Elastomeric Bearing Thrust Blocks Recovered from Accident Airplane



Photo 6 – Slider Ball Adjustment Collar and Set Screws (Courtesy of Accident Pilot)