

YEAR: 2014 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
4/14			180.0	I CERTIFY THAT THIS AIRCRAFT ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH SCOPE AND DETAIL 3543, APPENDIX D, ANNUAL CONDITION INSPECTION CHECKLIST AND DETERMINED TO BE IN CONDITION FOR SAFE OPERATION. REPLACE NGK'S SPARK PLUGS .018 gap Replaced fuel lines, fuel filters, rebuilt Mikuni FUEL PUMP WITH MIKUNI FUEL PUMP Rebuild kit, Rebuild both Bing CARBS w/ Bing carb rebuild kits, replace drive gear oil. ANDREW A. ZIGMANTAS RI [REDACTED] [REDACTED]