



Photo 1 – Digital Photograph Provided by Owner. View of the Aircraft at the Accident Site.



Photo 2 - Digital Photograph Provided by Owner. Forward View of the Aircraft Following Recovery




Photo 3 - Digital Photograph Provided by Owner. View Depicting the Piston Sides of the Forward Cylinder. No Scuffing or Scoring was Noted on the Piston. Hone marks are Visible on the Rear Cylinder Walls



Photo 4 - Photo 3 - Digital Photograph Provided by Owner. View Depicting the Piston Sides of the Rear Cylinder. No Scuffing or Scoring was Noted on the Piston. Hone marks are Visible on the Forward Cylinder Walls