

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>2014</u>	Total Time in Service	Description
Date: <u>05-02</u>	<u>Ø</u>	Installed this new propeller on 1524SL
Next Inspection Due: <u>H0665</u>	Time Since Overhaul	5th T34-203DC. Dynamically balanced propeller
<u>1557.6</u>	<u>NA</u>	to .03 I.P.F. All ops normal. - Southern field Aviation
		Mech. Cert. # or Repair Station # <u>[REDACTED] APP</u>
Year: <u>2015</u>	Total Time in Service	Description
Date: <u>03-26</u>		H0665 1987.1 - Performed 100% inspection.
Next Inspection Due:	Time Since Overhaul	Greased prop hub with Aeroshell #16 grease.
	<u>429.5</u>	Southern field Aviation
		Mech. Cert. # or Repair Station # <u>[REDACTED] APP</u>
Year: <u>2015</u>	Total Time in Service	Description
Date: <u>06-18</u>		Performed 100% Insp. greased prop w/
Next Inspection Due: <u>H0665</u>	Time Since Overhaul	Aeroshell #16 grease.
<u>2148.9</u>	<u>591.5</u>	Southern field Aviation
		Mech. Cert. # or Repair Station # <u>[REDACTED] APP</u>

Yea

Dat

Nex

Due

Yea

Dat

Nex

Due

Yea

Dat

Nex

Due