




**NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Wreckage Photo Array**

**ERA15LA273**



**Photo 1 – Runway Scars and Airplane (Photo Courtesy of FAA)**



**Photo 2 – Close Up View of Runway Scars (Photo Courtesy of FAA)**



**Photo 3 – Airplane – View from Front (Photo Courtesy of FAA)**



**Photo 4 – Airplane Belly and Main Landing Gear (Photo Courtesy of FAA)**



**Photo 5 – Left Inner Main Landing Gear Door (Photo Courtesy of FAA)**



**Photo 6 – Right Inner Main Landing Gear Door (Photo Courtesy of FAA)**



Photo 7 – Cockpit Gear Lever (Photo Courtesy of FAA)



**Photo 8 – Nose Gear Damage (Photo Courtesy of FAA)**