



Photo 1 –Wreckage as Found (FAA)



Photo 2 – Side View of Wreckage as Found (FAA)



Photo 3 – Aerial View of Initial Ground Scar and Wreckage as Found (FAA)




Photo 4 – Engine as Delivered from Quarantine for Exam (FAA)




Photo 5 – View of Metal Fragments and Bearing Material in Oil Sump as Found (FAA)



Photo 6 – View of Impact Damage to #3 Piston Skirt (FAA)



Photo 7 – View of Distressed and Fractured Main Bearing Journal (FAA)