



Photo 1 – Right Wing Damage (FAA Photo)



Photo 2 – Right Wing Damage (FAA Photo)



Photo 3 – Empennage Damage (FAA Photo)