



Photo 1 – Panoramic View of Accident Scene looking down to valley



Photo 2 - Initial Tree Strike



Photo 3 - View of Airplane at Rest Viewed from uphill



Photo 4 - View of Airplane at Rest from Below the Wreckage



Photo 5 - Backup Attitude Indicator and Airspeed indicator as found



Photo 6 - Engine after Extraction from the Ground



Photo 7 - Crankshaft Striation as found



Photo 8 - Propeller Blades after Removal from the Impact Crater