



Photo 1 – View of main wreckage in wooded area



Photo 2 - View of right side of engine



Photo 3 - View of rear of engine



Photo 4 - View of front of engine and damaged propeller



Photo 5 - View of left side of engine



Photo 6 – View of propeller removed from flange showing twisting and bending