



Photo 1 – NTSB Digital Photograph. Theodolite Image of the Submerged Wreckage



Photo 2 - NTSB Digital Photograph. View of the Wreckage Being Towed to Shore For Recovery



Photo 3 - NTSB Digital Photograph. View of the Empennage Before Recovery from the Water



Photo 4 - NTSB Digital Photograph. View of the Right Side of the Empennage Before Recovery from the Water. Note the Position of the Right Elevator Trim Tab



Photo 5 - NTSB Digital Photograph. Left Side View of the Left Elevator, Elevator Trim Tab, and Portions of Vertical and Horizontal Stabilizer and Rudder.



Photo 6 - NTSB Digital Photograph. Right Side View of the Wreckage During Recovery from the Lake



Photo 7 - NTSB Digital Photograph. View of the Autopilot Mode Controller



Photo 8 - NTSB Digital Photograph. View of the Autopilot Mode Annunciator Panel



Photo 9 - NTSB Digital Photograph. View of the Pilot's Control Yoke.




Photo 10 - NTSB Digital Photograph. View of the Elevator Trim Indicator



Photo 11 - NTSB Digital Photograph. View of the Engine and Propeller Assembly



Photo 12 - NTSB Digital Photograph. View of the Connections for Trim and Pitch Trim Servos




Photo 13 - NTSB Digital Photograph. View of the Connections at the Autopilot Flight Computer



Photo 14 - NTSB Digital Photograph. Close-Up View of the Autopilot Trim Switch Assembly