


# ***Turbine Power Technologies, Inc.***



1340 Flightline Blvd.  
DeLand, FL. USA. 32724  
Tell/Fax: (386) 873-2982  
[www.turbinepowertech.com](http://www.turbinepowertech.com)  
E-mail: [turbinepowertech@yahoo.com](mailto:turbinepowertech@yahoo.com)

Doug Brazy and Michael Pupek  
[REDACTED]

03-03-2016

ref: N401PT report 1

Work was done to Lancair N401PT on Jan 25th 2016. Removed our loaner starter generator and reinstalled the original starter generator. Once loaner was removed we noticed that it had been burnt out because they had never allowed the amperage to settle down after start before turning on the electric A/C. The aircraft left before we were able to do a logbook entry or invoice.

The repair work that was done to the nose gear doors was performed by Gintas also based at Deland. The repair was necessary due to side wind loading from uncoordinated take off and excessive gear operation speeds.

Regards  
Quentin Cokinogenis

Q. Cokinogenis