



Photo 1 – Tree canopy showing initial impact point



Photo 2 – Main wreckage



Photo 3 – View of damaged outboard right wing



Photo 4 - View of damaged inboard right wing



Photo 5 – View of damaged outboard left wing



Photo 6 – View of damaged right elevator



Photo 7 – View of damaged right horizontal stabilizer



Photo 8 – View of damaged left horizontal stabilizer and left elevator



Photo 9 – View of damaged vertical stabilizer and rudder



Photo 10 – View of fire damaged inboard left wing



Photo 11 – View of fire damaged empennage



Photo 12 – Front view of damaged engine



Photo 13 – Top view of engine



Photo 14 – Left side view of engine



Photo 15 – Right side view of engine



Photo 16 – Rear view of engine



Photo 17 – Front view of propeller showing damaged blades



Photo 18 - Top view of propeller showing damaged blades



Photo 19 - View of damaged propeller hub