



Photo 1 – NTSB Digital Photograph. View taken at Departure End of East Runway Looking to the West.



Photo 2 – NTSB Digital Photograph. View Taken East of Departure End of East Runway, Looking towards Accident Site.



**Photo 3 - Screenshot from Video Taken by Airstrip Owner. Left Side View Taken Abeam Camera Operator Location.
Note the Position of the Flaps and Elevator**



Photo 4 - Screenshot from Video Taken by Airstrip Owner. Rear View Depicting the Airplane Being Airborne Past the Windsock



Photo 5 - Screenshot from Video Taken by Airstrip Owner. Rear View Depicting the Airplane in a Left Roll and Nose-High Attitude While Airborne Past the Windsock. Note the Windsock Depicting The Wind From the West.



Photo 6 - Screenshot from Video Taken by Airstrip Owner. Rear View Depicting the Airplane in a Right Roll and Nose-High Attitude Just Before Impact.



Photo 7 - NTSB Digital Photograph. View Depicting the Left Wingtip in a Tree.



Photo 8 – NTSB Digital Photograph. Left Side View of the Wreckage. Note the Extensive Fire Damage to the Cockpit and Fuselage.



Photo 9 - NTSB Digital Photograph. View of the Tail Tie Down With Dirt Adhering to It.



Photo 10 - NTSB Digital Photograph. View Depicting 14 Inch Length of Tree Limb With Cuts at Both Ends.



Photo 11 - NTSB Digital Photograph. View of the Propeller and Engine Assembly. Note the Fractured Blade on the Left and Deformed Blade on the Right.



Photo 12 - Textron Aviation Digital Photograph. View Depicting the Carburetor Float. Note the Separated Float on the Left and the Resolidified Solder On the Bottom of the Separated Float.



**Photo 13 - Textron Aviation Digital Photograph. View Depicting the Attached Carburetor Float and the Solder Joint.
Note the Discoloration of the Float.**



Photo 14 - NTSB Digital Photograph. View of the Internals Of the Left Magneto.



Photo 15 - NTSB Digital Photograph. View of the Internals Of the Right Magneto.