



**Photo 1 – View of Wreckage Path Facing Opposite Direction of Travel (PSP)**



**Photo 2 – View of Main Wreckage Facing Opposite Direction of Travel (Lycoming)**



**Photo 3 – View of Cockpit Facing Direction of Travel (Lycoming)**



**Photo 4 – View of Left Engine After Recovery (Lycoming)**



**Photo 5 – View of Right Engine After Recovery (Lycoming)**



**Photo 6 – View of Angularly Cut Wood Recovered from Crash Site (Lycoming)**