

27-Oct-2015 1523 UTC | 30.354578, -88.682167
Ocean Springs, MS 39564, USA



Photo 1 – Fuselage Section with Partial Registration (Provided by MS Dept. of Marine Resources)



Photo 2 – Airplane Debris on Hangar Floor (Provided by FAA)



Photo 3 – Airplane Fuselage Section with Partial Restraint (Provided by FAA)



Photo 4 - Rudder and vertical stabilizer (Provided by FAA)