



Photo 1 – FAA Digital Photograph. View Following Recovery Depicting the Damage to the Left Wing and Separated Nose Landing Gear



Photo 2 - FAA Digital Photograph. View Following Recovery Depicting the Damage To One Propeller Blade.



Photo 3 - FAA Digital Photograph. View Following Recovery Depicting the Damage To Other Propeller Blade