




Photo 1 – Photograph Provided by Recovery Company. Left Forward Quartering View of the Left Side of the Airplane



Photo 2 - Photograph Provided by Recovery Company. View of the Right Main Landing Gear



Photo 3 – FAA Digital Photograph. View Depicting the Right Main Landing Gear, Right Brake, and Right Brake Line Before Being Disconnected by Recovery Crew



**Photo 4 - FAA Digital Photograph. View Depicting the Right Brake Caliper, Brake Disk, and Portion of Right Tire.
Note the Blue Discoloration on portions of the Brake Disk**



Photo 5 - FAA Digital Photograph. View Depicting Fluid Draining from Loosened Line at Left Brake Caliper