



Photo 1 – FAA photo- Left landing gear strut protruding from top of left wing



Photo 2 – FAA photo- View of under wing showing left flap damage



Photo 3 – FAA photo-View of spar damage



Photo 4 – FAA photo-view of strut separated in wing