



Photo 1 – Tailrotor Blade Damage (Photo Courtesy of FAA)



Photo 2 – Aft Vertical Cowling (Photo Courtesy of FAA)



Photo 3 – Fastener (Photo Courtesy of FAA)