



Photo 1 – Photograph Provided by Recovery Personnel. View of the Aircraft at the Accident Site.



Photo 2 - Photograph Provided by Recovery Personnel. View of the Canopy at the Accident Site



Photo 3 - Photograph Provided by Recovery Personnel. View of the Cockpit Showing the Detached Canopy



Photo 4 - Photograph Provided by Recovery Personnel. View of the Extended Engine and Propeller



Photo 5 - Photograph Provided by Recovery Personnel. View of the Canopy. Note the Position of the Left and Right Canopy Latches



Photo 6 - Photograph Provided by Recovery Personnel. View of the Right Canopy Latch Handle



Photo 7 - Photograph Provided by Recovery Personnel. View of the Left Canopy Latch Handle



Photo 8 - Photograph Provided by Recovery Personnel. View of the Right Canopy Latch Assembly Depicting the Pin Extending Beyond the Canopy Frame



Photo 9 - Photograph Provided by Recovery Personnel. View of the Left Canopy Latch Assembly Depicting the Pin Extending Beyond the Canopy Frame



Photo 10 - Photograph Provided by Recovery Personnel. View of the Left Canopy Latch Pin Receiver



Photo 11 - Photograph Provided by Recovery Personnel. View of the Right Canopy Latch Pin Receiver