



Photo 1 – Digital Photograph from NTSB Duty Officer. Right Forward Quartering View of the Airplane at the Accident Site.



Photo 2 - FAA Digital Photograph. View of the Fractured Inlet of the Fuel Strainer.



Photo 3 - FAA Digital Photograph. View of the Stain on the Ground Beneath the Engine.



Photo 4 – CMI Digital Photograph. View of the Fuel Drained from the Fuel Strainer.




Photo 5 - CMI Digital Photograph. View of the Fuel Drained from the Carburetor Bowl.



Photo 6 - CMI Digital Photograph. Forward View of the Propeller and Engine Assembly.



Photo 7 - FAA Digital Photograph. View of the Fuel Quantity Gauge.