



Photo 1 – FAA Digital Photograph. View of the Helicopter at the Accident Site.



Photo 2 - FAA Digital Photograph. View of the Helicopter at the Accident Site. Note a portion of the Main Rotor Mast and Portions of Both Main Rotor Blades, with Corresponding Burn Damage.



Photo 3 - FAA Digital Photograph. View of the Tailrotor Gearbox with Portions of both Tail Rotor Blades Visible.



Photo 4 - FAA Digital Photograph. View of the Engine Assembly



Photo 5 - FAA Digital Photograph. View Showing 3 of the 4 Transmission Struts, 2 of Which remained connected and 1 was Pulled Free From Its Attach.



Photo 6 - Digital Photograph Provided by Pilot. View Depicting Both Collective Springs and Cables.