



Photo 1 –View of main wreckage



Photo 2 -View of broken emmpenage