



No evidence of main rotor contact with tail boom

Photo 1 – FAA photo-View of tail boom buckled



Photo 2 – FAA photo-View of bent main rotor blades and helicopter laying on its left side