




Photo 1 – Side view of engine with bird feathers in cowling. (Courtesy of FAA)



Photo 2 – Front View of Propeller with View of Damaged Right Wing in Background (Courtesy of FAA)