



Photo 1 – Pre-Accident Right Side Photo Of The Accident Airplane Provided by Flying Club



Photo 2 – NTSB Digital Photograph. View of Outboard Portion of Right Wing Located in Tree.



Photo 3 - NTSB Digital Photograph. View of Outboard Portion of Right Wing Located in Tree, and Tree Damage.



Photo 4 - NTSB Digital Photograph. View of Wreckage Along Energy Path.



Photo 5 - NTSB Digital Photograph. Another View of Wreckage Along Energy Path.



Photo 6 - NTSB Digital Photograph. Right Side View of Empennage, Vertical Stabilizer, and Rudder.



Photo 7 - NTSB Digital Photograph. View of the Engine Assembly At Accident Site.



Photo 8 – NTSB Digital Photograph. View of the Separated Instrument Panel With Attached Attitude Indicator, and Directional Gyro.




Photo 9 - NTSB Digital Photograph. View of the Rear Portion of the Inverted Engine Following Recovery. Note the Missing Engine Accessories.



Photo 10 - NTSB Digital Photograph. View of the Propeller. Note the Blade Bending.



Photo 11 – NTSB Digital Photograph. Right Rear Quartering View of the Reconstructed Wreckage. Note the Fragmentation.



Photo 12 - NTSB Digital Photograph. View Showing the Fragmented Wreckage.