



Photo 1 – View of Main Wreckage as Found (Textron)



Photo 2 – View of Engines as Found (Textron)



Photo 3 – View of Right Engine Propeller Blades after Recovery (Textron)



Photo 4 - View of Left Engine Propeller Blades after Recovery (Textron)



Photo 5 – View of Left Engine Turbocharger Impeller (Textron)



Photo 6 - View of Right Engine Turbocharger Impeller (Textron)



Photo 7 - View of Angularly Cut Wood at Crash Site (Textron)