



Photo 1 –Breach in Airport Security Fence



Photo 2 – Close Up Photograph of Breach



Photo 3 – Debris Field



Photo 4 – Propeller Prior to Removal from the Ground



Photo 5 – Left Wing and Wing Tip



Photo 6 – Main Wreckage



Photo 7 - Empennage



Photo 8 – Right Wing



Photo 9 -Left Wing Tip Drag Mark




Photo 10 – Energy Path – Courtesy of Cirrus Aircraft




Photo 11 – Relationship of Ground Scars to the Debris Field – Courtesy of Cirrus Aircraft



Photo 12 – Propeller After Removal from Ground



Photo 13 – Leading Edge Gouging on Propeller Blade



Photo 14 – Fractured Crankshaft



Photo 15 – Close Up Photograph of Fractured Crankshaft



Photo 16 – First Set of Nose Wheel Tire Marks and Wheel Pant Paint Transfers



Photo 17 - Second Set of Nose Wheel Tire Marks and Nose Wheel Pant Paint Transfers