



Photo 1 – Airplane impact and fire damage looking at left front quarter.



Photo 2 – Airplane impact and fire damage looking from the tail forward.



Photo 3 – Right wing damage and ground impact mark.



Photo 4 – Left profile of entire airplane impact and fire damage.



Photo 5 – Close up of fire damage at center of fuselage. Note the engine heat damage.



Photo 6 – Interior of engine after crankcase separation.