



Photo 1 – NTSB Digital Photograph. Left Rear Quartering View of the Wreckage at the Accident Site.



Photo 2 - NTSB Digital Photograph. View of the Engine Assembly at the Accident Site. Note the Ignition Control Module.



Photo 3 - NTSB Digital Photograph. Right Rear Quartering View of the Wreckage at the Accident Site.



Photo 4 - NTSB Digital Photograph. View of the Damage to One of the Main Rotor Blades.



Photo 5 - NTSB Digital Photograph. View of the Instrument Panel.



Photo 6 - NTSB Digital Photograph. View of the Remaining Section of the Fractured Main Rotor Blade that Was Buried in the Ground.




Photo 7 - NTSB Theodolite Digital Photograph. View of the Separated Main Rotor Blade with Location Depicted.



Photo 8 - NTSB Digital Photograph. Rear View of the Engine Assembly and Propeller.




Photo 9 - NTSB Digital Photograph. View Depicting the Separated Electrical Connection at the Ignition Control Module.



Photo 10 – Google Earth Plot Depicting Key Position of Components.