



Photo 1 – View of Airplane as Found (FAA)



Photo 2 – View of cracked engine case after recovery. (FAA)



Photo 3 – View of fractured crankshaft at No. 3 bearing journal. (FAA)



Photo 4 – View of Nut A fracture surface on raised-lip side of nut. (FAA)



Photo 5 – View of Nut A with exposed bolt threads on flat side of nut. (FAA)