



Photo 1 – Left Side View of Main Wreckage – Courtesy of Morristown Municipal Airport



Photo 2 – Front View of Main Wreckage – Courtesy of Morristown Municipal Airport



Photo 3 – Right Side View of Main Wreckage – Courtesy of Morristown Municipal Airport



Photo 4 – Rear View of Main Wreckage – Courtesy of Morristown Municipal Airport



Photo 5 - Close Up of Nose Section Showing Propeller and Rudder Damage – Courtesy of FAA



Photo 6 – Propeller Tip – Courtesy of FAA



Photo 7 – Other Propeller Tip – Courtesy of FAA



Photo 8 – Separated Section of Rudder – Courtesy of FAA



Photo 9 – Gap in Rudder / Fuselage Juncture – Courtesy of FAA



Photo 10 – Ground Down Section of Rudder – Courtesy of FAA



Photo 11 – Damaged Front Engine Exhaust Pipe and Lower Cowling – Courtesy of FAA



Photo 12 – Landing Gear Actuation Handle – Courtesy of FAA




Photo 13 – Nose Gear Down Lock Displaying Minimal Contact with Pivot Shaft – Courtesy of FAA