



Photo 1 – Main Wreckage, View of Under Side (FAA Photo)



Photo 2 – Main Wreckage, After Recovery (NTSB Photo)



Photo 3 – Carburetor (FAA Photo)



Photo 4 – Carburetor Inlet Screen (FAA Photo)



Photo 5 – Damaged Propeller Flange (NTSB Photo)



Photo 6 – Engine and propeller (NTSB Photo)



Photo 7 – No. 1 Top Spark Plug (NTSB Photo)



Photo 8 - No. 2 Top Spark Plug (NTSB Photo)



Photo 9 - No. 3 Top Spark Plug (NTSB Photo)



Photo 10 - No. 4 Top Spark Plug (NTSB Photo)