



Photo 1 – Photo From Owner. Right Side View of the Fuselage, Engine Assembly and Propeller Following Recovery.



Photo 2 - Photo From Owner. Forward View of the Propeller and Engine Assembly Following Recovery. Note the Shattered propeller Blade.




Photo 3 - Photo From FAA. View of the No. 2 Cylinder Piston and Barrel. Note the Erosion of the Piston Edge Near the 1 O'Clock Position.