




Photo 1 – Airplane Wreckage inverted at Accident Site (FAA)



Photo 2 – Airplane Wreckage inverted at Accident Site (FAA)



Photo 3 - #2 Cylinder with View of Improperly Installed Tappet (NTSB)




Photo 4 - #3 Cylinder Tappet Assembly (NTSB)




Photo 5 - #2 Cylinder Tappet Assembly (NTSB)



Photo 6 - #1 Cylinder Tappet Assembly (NTSB)




Photo 7 - #4 Cylinder Tappet Assembly (NTSB)