



Photo 1 – Digital Photograph Provided by Operator. View of the Helicopter at the Accident Site. Note the Partially attached Tailboom.



Photo 2 - Digital Photograph Provided by Operator. View of the Dual Tachometer. Note the Lowest Numeric Marking of 50 on the Main Rotor.




Photo 3 – Digital Photograph Provided by FAA. Red Arrow Points to 1 Magnet Assembly Installed in C908-1 Yoke Assembly.




Photo 4 - Digital Photograph Provided by FAA. Red Arrow Points to Area on C908-1 Yoke Assembly with Missing Magnet Assembly.



Photo 5 - Digital Photograph Provided by Operator. Red Arrows Points to Both Main Rotor RPM Sender Assemblies.



Photo 6 - Digital Photograph Provided by FAA. Close-Up View. Red Arrow Points to 1 damaged Main Rotor RPM Sender Assembly.