




Photo 1 – View of fractured right main landing gear trunnion



Photo 2 – View of top of the fracture surface of the trunnion



Photo 3 – Close up of fracture surface of trunnion