



Photo 1 – FAA Digital Photograph. View of the Inverted Airplane at the Accident Site.



Photo 2 - FAA Digital Photograph. View of the Lower Surface of the Right Wing



Photo 3 - FAA Digital Photograph. View of Portion of the Lower Surface of the Left Wing. Note the blue Stain at the Fuel Vent Line and on Lower Wing Skin near Fuel Vent Line.



Photo 4 - FAA Digital Photograph. View of the As-Found Position of the Fuel Selector Valve.



Photo 5 - FAA Digital Photograph. View of the Upper Inboard Portion of Both Wings During the Process of Uprighting the Airplane.



Photo 6 - FAA Digital Photograph. View of the Propeller.



Photo 7 - FAA Digital Photograph. View Depicting the Approximately 6 ounces of Fuel Drained from the Un-breached Right Fuel Tank.



Photo 8 - FAA Digital Photograph. View Depicting the Approximately 2.5 gallons of Fuel Drained from the breached Left Fuel Tank