



Photo 1 – FAA Digital Photograph. View of the Airplane near the Accident Site



Photo 2 - FAA Digital Photograph. View of the Exterior of the Right Fuel Tank Strainer



Photo 3 - FAA Digital Photograph. View of the near complete blockage of the Right Fuel Tank Strainer



Photo 4 - FAA Digital Photograph. View of the organic material removed from Right Fuel Tank Strainer