

<u>NATIONAL TRANSPORTATION SAFETY BOARD</u>		Time 3:00 pm	Date 8/28/2017
RECORD OF: ☐ VISIT ☐ CONFERENCE ☒ TELEPHONE CALL			
Name (s) of Person (s) contacted or in conference and location		Routing	
FAA inspector- Inspector Juli O'Gorman		Symbol	Initials
Subject: N2804T-PA-28-140, Canton, GA. (CNI)			
Digest: In a telephone discussion with FAA inspector O'Gorman, during the examination of the it was noted that the carburetor linkage was striking the exhaust heat shield. This was preventing the throttle from its full movement. Due to the damage of the engine an engine run was not possible. A cursory examination did not reveal any anomalies other than the restricted movement of the throttle linkage.			
Conclusions, Action Taken, or Required:			
Date 8/28/2017	Title ASI	Signature Alleyne	