



Photo 1 – View of Airplane as Found as Viewed Facing Departure Runway (State of Vermont)



Photo 2 – View of Fractured Aileron Control Rod (State of Vermont)



Photo 3 – View of Deformed/Fractured Aileron Control Rod Pass-Thru Hole (State of Vermont)