



Photo 1 – Main Wreckage (Marion County Sheriff Photo)



Photo 2 – Tail Rotor (Marion County Sheriff Photo)



Photo 3 - Tail Rotor Blade Damage (Marion County Sheriff Photo)



Photo 4 - Tail Rotor Short Shaft Fracture (Marion County Sheriff Photo)



Photo 5 – Right Rear Skid Tube (Marion County Sheriff Photo)